




MITSUBISHI L200 (Triton) (KA; KB; 2.4; 2.5D; 3.2D)
MITSUBISHI Pajero Sport II (KH0; 2.5TD; 3.0; 3.2TD; 3.5)

2007
2008

14.1145 V2		05/08/15	1/7
------------	--	----------	-----





GB Location/Position Arrow



GB Movement Arrow










GB Screw Arrow







14.1145 V2

05/08/15


2/7







4



5

